DAMAGE ASSESMENT IN BOUAR, NANA MEMBERE PROVINCE, CENTRAL AFRICAN REPUBLIC

This map illustrates locations of destroyed structure in Bouar area, Central African Republic. Using a satellite image acquired 22 January 2014 by the WorldView-2 satellite, UNOSAT reviewed the town of Bouar and surrounding areas to locate signs of destroyed structures. A total of 336

underestimated due to the lack of previous image for comparison. Most destruction detected was most likely a result of burning given the blackened structural remains visible in the imagery. This is a preliminary analysis and has not yet been validated in the field. Please send ground feedback to UNITAR / UNOSAT.





Production Date: 19-Feb-14

Version 1.0



Activation Number. CE20131212CAF





Local/Urban Rd.

Satellite Data (1): WorldView-2 Imagery Dates: 22 January 2014 Resolution: 50 cm Copyright: DigitalGlobe, Inc. Source: US Department of State, Humanitarian Information Unit, NextView License Road Data: OSM (via bblike) Other Data: USGS, UNCS, NASA, NGA Analysis: UNITAR / UNOSAT_ Production: UNITAR / UNOSAT Analysis conducted with ArcGIS v10.1

Coordinate System: WGS 1984 UTM Zone 33N Projection: Transverse Mercator Datum: WGS 1984

The depiction and use of boundaries, geographic The depiction and use of boundaries, geographic names and related data shown here are not warranted to be error-free nor do they imply official endorsement or acceptance by the United Nations. UNOSAT is a program of the United Nations Institute for Training and Research (UNITAR), providing satellite imagery and related geographic information, research and analysis to UN humanitarian and development agencies and their implementing partners.

This work by UNITAR/UNOSAT is licensed under a Creative Commons Attribution-NonCommercial-ShareAlike 3.0 Unported License.





Contact Information: unosat@unitar.org 24/7 Hotline: +41 76 487 4998 www.unitar.org/unosat

